

Statement of Well Works sanctioned and in progress up to 9th March 1893.

Taluk.	Number of Works sanctioned.		No. of Works completed since last Meeting including old works.		Name of Works remaining to be completed with amount sanctioned.	Remarks.
	No.	Amount.	No.	Amount.		
	Old.	New.	Old.	New.		
Mysore.	6	5 1,315 4 0	Sinking a well at Harohalli ... 115 0 0 Do Gujagaudanpur ... 115 0 0 Do Jattihundi ... 100 0 0 Do Hoskote ... 125 0 0 Do Yedahalli ... 125 0 0 Do Salbandi ... 50 0 0 Deepening a Katte at Alavahalli ... 25 0 0 Repairing a cross road from Chatnahalli to Kadakola ... 175 0 0 Do from Anandur to Yelwal ... 250 0 0 Do Uttarahalli road ... 135 4 0 Repairing the stone Mantap on the Varuna Tank bund road ... 100 0 0 Total..... 1,315 4 0	Amildar asked to report progress.
Yedalore.	3	773 14 3	3	...	Well at Kesturkoppal ... 292 14 3 Do at Hebbalu ... 267 0 0 Do at Chikkavaddaragudi ... 214 0 0 Total 773 14 3	Work in progress.
Hunsur.	5	4 2,167 1 5	5	...	Well at Dharmapur ... 72 0 0 Do at Mallinathpur ... 180 0 0 Do at Banakuppe ... 37 14 5 Do at Bettadur ... 314 1 0 Levelling the tops ground for a bandy-stand ... 47 4 0 Opening out a new road to Periyapatam ... 500 0 0 Planting mango trees in the Musafarkhanas ... 57 14 0 Converting a pond into a draw-well at Periyapatam... 496 0 0 Sinking a well at Bettadapur... 462 0 0 Total..... 2,167 1 5	Work in progress. Do Work executed for 415-3-6. Work not commenced as the well has a little water.
Gundlupet.	2	1 382 12 0	Repairing Chandriyanakatte. ... 288 10 0 Well at Triyambakapur ... 64 0 0 Repairing a well at Chikkahalli ... 30 2 0 Total..... 382 12 0	Work proceeding. About half completed.
Heggaddevankote.	2	7 1,029 7 9	Repairing Kengersakatte ... 39 8 9 Do a pond near Kottagala ... 50 0 0 Sloping the sides of Hebbahalli and Taraka river ... 100 0 0 Well at Bhimanshalli ... 171 11 0 Do at Yerahalli ... 146 3 0 Do at Nanjannikenhalli ... 198 0 0	Amildar asked to report progress.